



# *COMMONWEALTH of VIRGINIA*

## *DEPARTMENT OF ENVIRONMENTAL QUALITY*

### NORTHERN REGIONAL OFFICE

13901 Crown Court, Woodbridge, Virginia 22193

(703) 583-3800

[www.deq.virginia.gov](http://www.deq.virginia.gov)

Matthew J. Strickler  
Secretary of Natural Resources

David K. Paylor  
Director

Thomas A. Faha  
Regional Director

### MEMORANDUM

To: Richard Doucette  
Land Protection and Revitalization Program Manager

From: Daniel J.C. Demers  
Waste Technical Coordinator

Re: IR# 2019-N-2076  
Gable Farm, Gable Farm Lane, Hamilton, VA  
Evaluation of Fill Material - February 22, 2019

---

On February 22, 2019, a site visit was conducted in response to complaints regarding fill material at the above referenced site. The meeting began at 10:00 am at Scott Jennings Park where Department of Environmental Quality (DEQ) personnel and Loudoun County staff had arranged to meet before driving to the site. Attendees from the DEQ included Nolan Compton, Daniel Demers, Richard Doucette, and Alan Lacy.

A brief review of the site history was presented by Loudoun County personnel and the landowner, Doctor Gable, which was followed by a site inspection. All of the fill material observed was in place and DEQ was informed that no site activity had occurred since November 2018 because of a stop work order from Loudoun County.

The fill material primarily contained soil, bricks, asphalt, concrete, and rocks. A nominal amount of woody vegetation, silt fence fabric, and PVC was also observed. Staff did not observe any evidence of contamination such as an oily sheen or chemical odor. The material appears to be exempt under the Virginia Solid Waste Management Regulations (9VAC 20-81), as per:

9VAC20-81-95.C.7.n - "Uncontaminated concrete and concrete products, asphalt pavement, brick, glass, soil, and rock placed in commerce for service as a substitute for conventional aggregate." and

9VAC20-81-95.D.11 - "Using rocks, block, dirt, broken concrete, crushed glass, porcelain, and road pavement as clean fill."

Site photos are attached.

**VIRGINIA DEPARTMENT OF ENVIRONMENTAL QUALITY  
DIVISION OF LAND PROTECTION AND REVITALIZATION  
Northern Regional Office**

Photos have not been altered except to change the size of the file.

<b>Site Name:</b>	Gable Farms (IR# 2019-N-2076)	<b>Date:</b>	Feb. 22, 2019
<b>Address:</b>	Gable Farm Lane, Hamilton, Virginia	<b>Taken by:</b>	Richard Doucette
<b>County:</b>	Loudoun County	<b>Photo #:</b>	1 of 4



Photo 1. Back slope of fill along Gable Farm Lane. Facing Northeast.



**VIRGINIA DEPARTMENT OF ENVIRONMENTAL QUALITY  
DIVISION OF LAND PROTECTION AND REVITALIZATION  
Northern Regional Office**

Photos have not been altered except to change the size of the file.

<b>Site Name:</b>	Gable Farms (IR# 2019-N-2076)	<b>Date:</b>	Feb. 22, 2019
<b>Address:</b>	Gable Farm Lane, Hamilton, Virginia	<b>Taken by:</b>	Richard Doucette
<b>County:</b>	Loudoun County	<b>Photo #:</b>	2 of 4



Photo 2. Survey marker on a large block of concrete. Marker suggests that this block originated from a Metro Project.



**VIRGINIA DEPARTMENT OF ENVIRONMENTAL QUALITY  
DIVISION OF LAND PROTECTION AND REVITALIZATION  
Northern Regional Office**

Photos have not been altered except to change the size of the file.

<b>Site Name:</b>	Gable Farms (IR# 2019-N-2076)	<b>Date:</b>	Feb. 22, 2019
<b>Address:</b>	Gable Farm Lane, Hamilton, Virginia	<b>Taken by:</b>	Richard Doucette
<b>County:</b>	Loudoun County	<b>Photo #:</b>	3 of 4



Photo 3. Back slope of fill along Gable Farm Lane. Facing Northeast.



**VIRGINIA DEPARTMENT OF ENVIRONMENTAL QUALITY  
DIVISION OF LAND PROTECTION AND REVITALIZATION  
Northern Regional Office**

Photos have not been altered except to change the size of the file.

<b>Site Name:</b>	Gable Farms (IR# 2019-N-2076)	<b>Date:</b>	Feb. 22, 2019
<b>Address:</b>	Gable Farm Lane, Hamilton, Virginia	<b>Taken by:</b>	Richard Doucette
<b>County:</b>	Loudoun County	<b>Photo #:</b>	4 of 4



Photo 4. Back slope of fill along Gable Farm Lane. Facing Northeast.